## **BUILDING SAFETY CERTIFICATE**

NO. 3361/ Dog Bo/2024

Dated: 20/04/2024

It is certified that the existing building of Podar International School Akola at Survey No. 50/1, 51/2,

Krushi Nagar Umri, Akola is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Blo ck (6)
No. of Floor(s) in the Block	Zero Basement 1 Ground Floor & 3 Upper Floors	NIL	NIL	NIL	NIL	NIL

The building is owned/ occupied by Podar International School Akola have complied with the Building safety requirements in accordance with NationalBuilding code Rules, and verified by the officers concerned of Executive Engined (Name of Department/ Govt.) on 29 04 2024 (Date of Inspection) in the Presence of Principal Podar International School, Akola Survey No. 50/1, 51/2 Krushi Nagar Umri Akola. PWDn Atola and that the building/premises is fit for occupancy for running school with effect from 29 ০০০ তি a period of ......one........ years in accordance with rule and subject to compliance of the specific 1. follow the sule National building code
2. Regular Inspection of five fightening instrument and highdrund.
3. Regular Inspection of building and maintance also Electrical Instrument.
4. Exit Board Displays on well conditions as appended.

Signature with Seal \_\_nw

Name prasad pati

Designation Executive

Name & Address of Department/ Office: PMD Division

Podar International School

Podar International School. Akola Aff. No. 1130436