

BULDING SAFETY CERTIFICATE

No. 951

Dated :01/07/2024

It is certified that the existing building **Podar International School, Baramati** at Gat No.612 Bandalwadi(Gunawadi),Indapur road Tal-Baramati Dist-Pune is having blocks/floors as per details below:

Details of Blocks in school	BLOCK 1	BLOCK 2	BLOCK 3	BLOCK 4	BLOCK 5
No.of floors in the block	G+2	Not Applicable	Not Applicable	Not Applicable	Not Applicable

The building is owned/occupied by **Podar International School, Baramati**, at Gat No.612 Bandalwadi(Gunawadi),Indapur road Tal-Baramati Dist-Pune have complied with the building safety requirements in accordance with National Building code rules and verified by the officers concerned of **Public Work Department Sub Division Baramati** on **28/06/2024** in the presence of **shri.Shekhar Tupe**, (Asst.Admin Manager, Podar International School, Baramati) That the building/premises is fit for occupancy for running school with effect from **01/07/2024 to 30/06/2027** for period of **3(three)** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Building colour needs to be done in regular intervals
2. Anti termite treatment for building and furniture
3. Check the water pipeline, electricity and sanitary system regularly.
4. Immediate repair needs to be done if anything happens due to natural calamities.

Issued on **01/07/2024** at office by



(S.A. Patil)

Asst. Engineer Grade-1

P.W. Sub Division Baramati